

University of Bielefeld - Faculty of technology
Networks and distributed Systems

Research group of Prof. Peter B. Ladkin, Ph.D.

[Back to Abstracts of References and Incidents](#)

[Back to Root](#)

Lauda Air B767 Accident Report

Prepared for the WWW by

Hiroshi Sogame
Safety Promotion Comt.
All Nippon Airways



AIRCRAFT ACCIDENT INVESTIGATION COMMITTEE MINISTRY OF TRANSPORT AND COMMUNICATIONS THAILAND

**LAUDA AIR LUFTFAHRT AKTIENGESELLSCHAFT
BOEING 767-300ER
REGISTRATION OE-LAV
DAN CHANG DISTRICT
SUPHAN BURI PROVINCE
THAILAND
26 MAY B.E. 2534 (A.D. 1991)**

**CAB APPROVED
JULY 21, 1993**

	CONTENTS	
	<u>SYNOPSIS</u>	1
1	<u>FACTUAL INFORMATION</u>	
1.1	<u>History of Flight</u>	2
1.2	<u>Injuries to Persons</u>	3
1.3	<u>Damage to Airplane</u>	3
1.4	<u>Other Damage</u>	3
1.5	<u>Personnel Information</u>	4
1.6	<u>Airplane Information</u>	4
1.7	<u>Meteorological Information</u>	6
1.8	<u>Aids to Navigation</u>	7
1.9	<u>Communications</u>	7
1.1	<u>Aerodrome Information</u>	7
1.11	<u>Flight Recorders</u>	7
1.12	<u>Wreckage and Impact Information</u>	8
1.13	<u>Medical and Pathological Information</u>	8

1.15	<u>Survival Aspects</u>	9
1.16	<u>Tests and Research</u>	9
1.17	<u>Additional Information</u>	12
1.18	<u>Useful or Effective Investigation Techniques</u>	13
2	<u>ANALYSIS</u>	
2.1	<u>General</u>	14
2.2	<u>Airplane Wreckage and Structural Failure Analysis</u>	17
2.2.1	<u>Airplane Wreckage</u>	17
2.2.2	<u>In-Flight Breakup Sequence</u>	18
2.2.3	<u>Fire Damage</u>	19
2.3	<u>Engineering Simulation</u>	21
2.4	<u>Thrust Reverser Certification</u>	27
2.5	<u>Possible Thrust Reverser Failure Modes</u>	30
2.5.1	<u>General</u>	30
2.5.2	<u>Crew Commanded Deployment</u>	31
2.5.3	<u>Electrical System Failures Resulting in Deployment</u>	32
2.5.4	<u>Hydraulic System Failures Resulting in Deployment</u>	33
2.6	<u>Maintenance Activity</u>	35
2.7	<u>System Design Changes as a Result of the Accident</u>	36
	ii	
2.8	<u>Flight Data Recorder Damage</u>	38
3	<u>CONCLUSIONS</u>	
3.1	<u>Findings</u>	40
3.2	<u>Probable Cause</u>	42
4	<u>RECOMMENDATIONS</u>	43
5	<u>APPENDIXES</u>	
	<u>Appendix A--Cockpit Voice Recorder Transcript Extract</u>	44
	<u>Appendix B--Wreckage Distribution Diagram</u>	58
	<u>Appendix C--Thrust Reverser System General Description</u>	59
	<u>Appendix D--U.S. National Transportation Safety Board</u>	
	<u>Urgent Action Safety Recommendations 91-45 through 91-48</u>	69
	<u>Appendix E--U.S. Federal Aviation Administration Letter</u>	
	<u>Dated September 11, 1991</u>	74
	<u>Appendix F--Diagram 767 PW 4000 Thrust Reverser, Current/New System</u>	79
	<u>Appendix G--Comments of Accredited Representatives</u>	80

iii

AIRCRAFT ACCIDENT
INVESTIGATION COMMITTEE
LAUDA AIR LUFTFAHRT AKTIENGESELLSCHAFT
BOEING 767-300ER
REGISTRATION QE-LAV
BAN DAN CHANG DISTRICT
SUPHAN BURI PROVINCE
THAILAND
26 MAY B.E. 2534 (A.D 1991)

SYNOPSIS

Lauda Air airplane, Boeing 767-300 ER of Austrian nationality and registry OE-LAV, flight number NG 004 was on a scheduled passenger flight Hong Kong-Bangkok-Vienna, Austria. NG 004 departed Hong Kong Airport on May 26, 1991, and made an intermediate landing at Bangkok Airport for unloading and loading of passengers and cargo. The flight departed Bangkok Airport at 1602 hours. The airplane disappeared from air traffic radar at 1617 hours about 94 nautical miles northwest of Bangkok. Local police authorities near the accident site notified the Rescue Co-ordination Centre, Department of Aviation in Bangkok of the accident. The Department of Aviation notified aviation authorities in the Republic of Austria (state of the operator and state of registry) and the United States of America (state of manufacture). The Republic of Austria and the United States of America sent their Accredited Representatives to participate in the investigation.

All times in this report are UTC.

2

1. FACTUAL INFORMATION

37

1. Replacing the solenoid operated Hydraulic Isolation Valve (HIV) with a motor-operated Hydraulic Isolation Valve.
2. Adding a dedicated stow valve.
3. Adding new electric wiring from the electronics bay and flight deck to the engine strut. Critical wire isolation and protective shielding is now required.
4. Adding a new reverser test/reverser system maintenance indication panel in the cockpit.
5. Replacing existing reverser stow proximity targets with improved permeability material to reduce nuisance indications.
6. Adding a thrust reverser deploy pressure switch.

The original design of the B767/PW4000 thrust reverser system required multiple failures for the reverser to deploy in-flight. The changes listed above for the B767 thrust reverser system address each of possible failure modes identified as a result of the investigation. The design changes effectively should prevent in-flight deployment even from multiple failures. A diagram of the current (at the time of the accident) and new thrust reverse system is included in this report as appendix F.

Thrust reverser system reviews are continuing on other model series airplane.

38

2.8 Flight Data Recorder Damage

The recording tape media within the FDR installed on the accident airplane was melted due to thermal exposure related to the post crash fire. It was impossible to extract any information from the recorder. Industry records indicate that investigative authorities have reported a similar loss of recorded data in several accidents that occurred both prior to and subsequent to the subject accident. These events are:

March 10, 1989	Dryden, Ont., Canada	F28	Air Ontario
November 27, 1989	Bogota, Colombia	B727	Avianca
December 29, 1991	Taipei, Taiwan	B747F	China Airlines
January 20, 1992	Strasbourg, France	A320	Air Inter

The Technical Standard for FDRs contains a minimum performance requirement for heat exposure from flame of 1100 degrees Celsius to cover 50% of the recorder for 30 minutes.

There were some similar circumstances in each of the above mentioned accidents in that the crash site was located off airport property. It was not possible for fire department vehicles to gain rapid access to the site. In each case, the FDR was involved in a ground fire which became well established and involved surrounding debris. There does not appear to be a way to determine the exact duration of heat exposure and temperature level for the involved FDR in any of these accidents. However, it has been recognized that ground fires including wood forest materials and debris continued in these instances for at least six to twelve hours. The thermal damage to the tape recording medium was most probably the result of prolonged exposure to temperatures below the 1100 degree testing level but far in excess of the 30 minute test duration.

39

It is recommended that the airplane certification authorities and equipment manufacturers conduct research with the most modern materials and heat transfer protection methods to develop improved heat protection standards for flight data recorders. Standards revisions should include realistic prolonged exposure time and temperature levels. The revised standards should apply to newly certificated FDR equipment and where practical through Airworthiness Directive action, to FDRs that are now in service.

40

3. CONCLUSIONS

3.1 Findings

1. The crew members were trained, qualified, and certificated for their respective duties according to the laws and regulations of the Republic of Austria.
2. The airplane was certificated, equipped and maintained, and operated according to regulations and approved procedures of the Republic of Austria.
3. The weather in the area was fair. There were no reported hazardous weather phenomena although lightning may have been present. It is possible that the horizon was not distinguishable.
4. The physical evidence at the crash site showed that the left engine thrust reverser was in the deployed position.
5. Examination of nonvolatile computer memory within the left EEC indicated that the engine was at climb power when the reverser deployed, engine thrust was reduced to idle with the reverser deployment, and the recorded Mach number increased from 0.78 to 0.99 after the deployment. The actual maximum speed reached is unknown due to pressure measurement and recording

6. The scatter of wreckage indicated that the airplane experienced in-flight breakup at a steep descent angle and low altitude.

41

- 42

- ### 3.2 Probable Cause

43

BY THE AIRCRAFT ACCIDENT INVESTIGATION COMMITTEE OF THAILAND

EXPERT
EXPERT
EXPERT
EXPERT
EXPERT
EXPERT
MEMBER AND
SECRETARY
MEMBER AND
ASSISTANT
SECRETARY